RESEARCH REPORT DOCUMENTATION PAGE

		Contract No.				
1. Report No.	2. Report Date			4. Project No. NH-5-085(041)041		
MR 2002-01 5. Title and Subtitle	March 2003	6. Report Type 7. Project No.				
J. THE AND SUBME					7. Project No.	
Microsurfacing Performance E	Click on link to open report		8. Project No.			
Thioresanding Ferromance Evaluation			Work Plan [
			Construction		9. Project No.	
				-		
			Evaluation [⊣ Γ	10. Project No.	
			Final [_		
11. Author(s)/Principle Investigator(s)						
Kyle Evert						
12. Performing Organization Name and Addre	ess		Sponsoring Agency Name	and Addre	SS	
NDDOT M+R ⊠	DOT M+R 🛛 North Dakota DOT			North Dakota DOT		
NDDOT OTHER* □	Materials and Res	Materials and Research Division				
NDSU	300 Airport Road		300 Airport Road			
UND	Bismarck ND 585	Bismarck ND 58504-6005				
UGPTI 🗆		DISTILLICK IND 30			4-6005	
OTHER*						
*see supplementary notes						
14. Supplementary Notes						
The Supplementary (1885)						
15. Abstract						
Purpose and Need						
•						
Microsurfacing is a polymer modified cold mix paving system that can remedy a broad range of pavement distresses. It can be used to repair; rutting and shoving, improve surface friction, and restore the road profile with minimal surface preparation.						
<u>Objective</u>						
This study will evaluate the performance and cost effectiveness of microsurfacing as a method to fix rutting and depressed transverse cracks in a rural highway segment.						
<u>Scope</u>						
The physical characteristics the two sections will be compared to are; distresses, overall surface condition, performance, ride, and skid resistance.						
These physical characteristics will be evaluated by the pathways van annually. The evaluation period for this project will be 7-years or until failure. The project location is located on Highway 85 near Amidon.						
Construction						
Construction						
The construction of this project had a problem with the paving of the second lift of the microsurfacing section. The paving operation could not get a uniform product from the paver. The cause of this problem was due to operator error. The problem was corrected and the rest of the microsurfacing for the project was continued as planned. The project was completed on time and has improved the pavement surface.						
16. Key Words	17. Distribution Statement				18. No. of Pages	
		is document is availa	ble to the public from	m:	40	
Gradation						
Emulsion	North Dakota Department of Transportati				19. File type/Size	
Slurry				D.K. / 4.0		
Overlay	Materials and Research Division: 300 Airport Road Pdf / 1.3 mb				Pat / 1.3 mb	
Roughness Bismarck ND 58504-6005						
	Office: (701) 32		x: (701) 328 -0310			
	J.1100. (701) 02	-5 5555	(101) 020 0010			